

Comanche 1000-hr Gear AD Go-NoGo Gauge Kit

Below are photos of the Go / No-Go measuring kit put together by John Futter. It is used when performing the 1000-hr Gear AD Inspection on your Comanche and is available on loan from the Northeast Comanche Tribe.



Go-NoGo kit components

The kit contains certified gauges for hole and thread testing packaged in a metal case, with copies of the testing procedure for photo copying by the user.



packaged for shipping



document folder

The kit is held in Putnam CT and can be conveyed (shipped/carried/picked up) to the next user. Use is currently at no cost but a donation to the Northeast Comanche Tribe would be encouraged. For more information contact Pete Morse below.

Pete Morse piper32p@gmail.com
104 Woodside St. 401-636-1046
Putnam CT 06260